



Fig. 1

Fig. 2a




set sensors in Multidrop to address 15

Fig. 2b



address configured sensors

Fig. 2c



address free sensors and assign MPI

Fig. 3




Fig. 4




Fig. 5




Fig. 6

sensor address
0

Fig. 7

sensor association
MPI1 (configured) ▼
<u>list selection:</u>
MPI1 (configured / free)
MPI2 (configured / free)
none

Fig. 8

sensor addressing
serial number: 12345678
HART-address: 15

Fig. 9




Fig. 10

